



NOTE:

USE 9 INCH WIDE UNCURED FLASHING TAPE CUT IN HALF TO FORM THE FIRST WRAP AROUND THE PIPE. THE SECOND WRAP SHALL BE FORMED USING A FULL WIDTH OF 9 INCH WIDE UNCURED FLASHING TAPE.

MULE-HIDE
PRODUCTS CO., INC.
2005

Flexible Penetration

SYSTEMS:
 Fully Adhered 90mil System

DETAIL NO.:
MHE-510