


NOTE:
FOR ALL PIPES OVER 6 INCHES DIAMETER
FIELD MEMBRANE MUST BE MECHANICALLY
ATTACHED AT BASE OF COLLAR

BASE TARGET PATCH MAY BE CURED
MEMBRANE OR UNCURED FLASHING



NOTE: IF USING UNCURED FLASHING, PREP EPDM MEMBRANE AND PIPE WITH SEAM CLEANER PRIOR TO
APPLYING SPLICE ADHESIVE. IF USING FLASHING TAPE, PREP WITH TAPE PRIMER.

**MULE-HIDE
PRODUCTS CO., INC.
04/01/2004**

FIELD FABRICATED
HOT PIPE

SYSTEMS:
ALL

DETAIL NO.:
MHE-142