



NOTE:

1. FLASHING TAPES MAY BE SUBSTITUTED FOR UNCURED EPDM FLASHING
2. MINIMUM FLASHING HEIGHT TO BE 8" WHERE POSSIBLE



NOTE: IF USING UNCURED FLASHING, PREP EPDM MEMBRANE AND PIPE WITH SEAM CLEANER PRIOR TO APPLYING SPLICE ADHESIVE. IF USING FLASHING TAPE, PREP WITH TAPE PRIMER.

**MULE-HIDE
PRODUCTS CO., INC.
04/01/2004**

**FIELD FABRICATED
PIPE FLASHING**

**SYSTEMS:
ALL**

**DETAIL NO.:
MHE-141**